

Radiation Safety Poster: Personal Dosimetry Monitoring in X-ray Areas

- The dosimeters for whole body, collar and fetal monitoring have icons to identify the wear locations on your body.

Whole Body Dosimeter	Collar Dosimeter	Fetal Dosimeter	Eye Dosimeter (For project use only)
			
Wear on the front of the torso **between the waist and shoulder**. The label must away from the body. Place **under lead apron**.	Wear at the **front of the body at neck level**. The label must face away from the body. Place **over lead apparel.**	Wear at the **waist on the abdomen**. The label must face away from the body. Place **under lead apron.**	The label must face away from the body. **Surgeons:** clipped on glasses, headband, or cap in front of and as close to the **most exposed** eye as possible. **Other staff:** clipped on at the side close to the **most exposed** eye.

How to wear your dosimeter(s)?



Who wears personal dosimeter(s)?

- Dosimeters will be assigned where there is reasonable probability that a worker may receive more than 1 mSv annually.

How many dosimeters do you wear?

- The number and types of dosimeters assigned will depend on which department you work in and the type of work you do.

What do you need to do?

- Wear your dosimeters at all times during your shift.
- Never leave your dosimeters on protective apparel or near x-ray equipment/radioactive substances when not in use.
- Return your dosimeters to the badge storage location in your department after each shift.
- Never store dosimeters inside your locker, or take them home (except for regional workers like biomed staff)
- Review dosimeter reports and initial to acknowledge that you have review your dose.
- Inform your dosimetry contact person / administrator of any incident involving your dosimeters (accidental exposure, lost dosimeter, etc).

For More Information, contact your dosimetry contact person / administrator or the Site Radiation Safety Officer.

Retiring, resigning or on maternity/other leave: please notify your dosimetry contact person of your last date of work. Return your dosimeters to the contact person.